

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. J-12

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T14S R35E
S9
E1/16--
S16
1987
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 10" in the ground and raised a mound of stone around the pipe.

From Which:

A Fir 8" dia., Bears N53°W., 26.6 ft., scribed: E1/16 S9 BT

A Fir 8" dia., Bears S 2°W., 20.2 ft., scribed: E1/16 S16 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, North 10 ft. and West 5 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1983
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: July 7, 1987
Refer to Map of Survey No. 1009

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*6*..... day of.....*Nov*....., 19.....*87*.....
.....*Robert D. Baggett*..... by.....
(COUNTY OFFICIAL) (DEPUTY)