

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. R-9

History of original corner establishment:

Corner was originally established by
G.R. Campbell in July, 1901, under
General Land Office Contract No. 724.
U.S. Surveyor Generals Notes State:
Set iron stone 15x10x6 ins. 10 ins. in
the ground, for cor. of secs. 20,21,28 & 29,
marked with 2 notches on S and 4 notches
on E edges;

DIAGRAM

T14S R35E
S201S21
-.-
S291S28
1987
RLS 848

from which

A white fir 16 ins diam bears N41°E., 49 lks dist mkd T14S R35E S21 BT
A black pine 12 ins diam bears S52°E., 59 lks dist mkd T14S R35E S21(28)BT
A white fir 12 ins diam bears S40°W., 73 lks dist mkd T14S R35E S29 BT
A white fir 16 ins diam bears N25°W., 48.5 lks dist mkd T14S R35E S20 BT

Description of corner evidence found:

Found 16"x12"x6" stone with 4 marks on East face,
set vertical.

From Which:

Found the NE & NW Bearing trees as follows:

A Fir snag, 18" dia., with visible scribing, Bears
N44°E., 32.0 ft. (Record=N41°E., 32.3 ft.)

A Fir snag, 14" dia., with visible scribing, Bears
N18°W., 32.0 ft., (Record=N25°W., 32.0 ft.)

Accepted the above described stone as the Section
Corner position.

**Description of monument and accessories I established to perpetuate the
original location of this corner:**

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown
on the **DIAGRAM**, SET 18" in the ground, set the original stone North
alongside pipe and raised a mound of stone around pipe.

From Which:

New Bearing Trees

A Fir 8" dia., Bears N34°W., 17.8 ft., scribed: T14S R35E S20 BT

A Fir 10" dia., Bears N61°E., 27.7 ft., scribed: T14S R35E S21 BT

A Fir 12" dia., Bears S27°E., 29.3 ft., scribed: T14S R35E S28 BT

A Fir 14" dia., Bears S82°W., 26.8 ft., scribed: T14S R35E S29 BT

Measurements to trees taken with a metal tape and magnetic compass,
with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing
Tree Sign above blaze, and warning sign on back of each tree. Painted
a 6" red band at breast ht. around each tree. Set steel fence posts with
warning & Boundary Signs, North 5 ft. & East 4 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1963
DOUGLAS M. FERGUSON
848

This work is performed by:

Douglas M. Ferguson RLS 848

Mt. Vernon Oregon.

On: Aug. 3, 1987

Refer to Map of Survey No. 1009

Office of Surveyor County of Grant

State of Oregon, I hereby certify that the within instrument was filed in this office

for record on the 6 day of Nov, 1987

Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)