

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Nothing set in original survey

DIAGRAM

S 31
EWE 1/256

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 3" Aluminum cap on 2½" Aluminum pipe 30" long & buried 20" in ground with mound of stone to cap.



New Bearing Trees:

6" Spruce, N22°W, 17.6', Scribed EWE 1/256 S31, B.T.
4" Fir, N54°E, 18.7', Scribed X, B.T.

All B.T.'s have sign 54-4 & 54-3 attached. Set steel guard post with 54-9 & 54-2 sign, 3' west of monument. Painted red band around bearing trees. Tagged trees with L.S. 980 washer.

Witnesses: David Scott, Party Chief
Richard Larson, Chainman

MONUMENT STAMPED:



Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 14 day of Jan, 1981
Robert D. Dege by _____
(COUNTY OFFICIAL) (DEPUTY)