


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX NO. K-9

History of original corner establishment:

Corner not previously established.



Description of corner evidence found:

Corner not previously established


Description of monument and accessories established to perpetuate the original location of this corner:

Set 2-1/2"x30" galvanized iron pipe with 2-1/2" brass cap stamped as shown on the **DIAGRAM**, set 12" in the ground and raised a mound of stone and earth around the pipe.

From Which:

A Juniper 7" dia., Bears S33⁰E., 38.4 ft., Scribed: N1/16 S16 BT
A Fir 6" dia., Bears S20⁰W., 16.9 ft., Scribed: N1/16 S17 BT
Nailed brass washer stamped PLS 848 on blaze above BT Scribe,
Pearing Tree Sign above blaze and painted a 6" red band around each tree.

Measurements to trees taken with metal tape and bearings taken with theodolite which is oriented to the control survey.



Corner is set June 10, 1985
By Douglas M. Ferguson PLS 848
Ferguson Surveying & Engineering
Mt. Vernon Oregon.
Witnessed by J. David Brinton PLS 2065

Office of..... *Survey* County of..... *Grant*
State of..... *Oregon*, I hereby certify that the within instrument was filed in this office
for record on the..... *1* day of..... *July*, 19*85*
..... *Robert D. Brinton* by
(COUNTY OFFICIAL) (DEPUTY)

SEE MAP OF SURVEY NO. 870