


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Mark A. Fullerton under his General Land Office contract No. 395.

Surveyor General's records state:
Set basalt stone 15 x 12 x 9 in stone mound for cor. to Secs. 20, 21, 28 & 29.



Description of corner evidence found:

Found stone 15 x 11 x 9 in mound of small stones. Found two faint notches on South edge. Found no marks on East edge.

Description of monument and accessories established to perpetuate the original location of this corner

Set 2½" x 30" Alum pipe with 3" Alum cap marked as shown. Buried original stone next to pipe and built stone mound around pipe.

T15S	R26E
S20	S21
S29	S28
RLS 1104	1979

A Doug. Fir, 10 in. dia., bears N37°W 148.4', scribed T15S R26E S20, B.T.

A Pond. Pine, 7 in dia., bears N28°E 127.9', scribed T15S R26E S21, B.T.

A Juniper, 9 in. dia., bears S47°E 78.5', scribed T15S R26E S28, B.T.

A Doug. Fir, 9 in. dia., bears S44°W 95.1', scribed T15S R26E S29, B.T.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

James R. Tye

OREGON
JULY 22, 1977
JAMES R. TYE
1104

Michael Yardley

Witness to Corner: Michael Yardley
Chainman

I hereby certify the above monument was re-established as herein described on 7-18-79.

Office of Surveyor County of Grant
State of OR, I hereby certify that the within instrument was filed in this office for record on the 23 day of Aug, 1979, at 1:30 o'clock P.m., (signed)
Edward W. Dugan by _____
(COUNTY OFFICIAL) (DEPUTY)