


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Mark A. Fullerton under his General Land Office contract No. 395.

Surveyor General's records state:
Set basalt stone 18 x 16 x 7 in stone mound for cor. to secs. 27, 28, 33 & 34.



Description of corner evidence found:

Found stone 18 x 16 x 6 in stone mound with one notch on South edge. Found no distinct marks on East edge.

Description of monument and accessories established to perpetuate the original location of this corner

Set 2½" x 30" Alum. pipe with 3" Alum. cap marked as shown. Hit solid shale 12" deep. Set original stone next to pipe and built stone mound around pipe.

T15S R26E
S28 | S27
S33 | S34

RLS 1104 1979

- A Juniper, 8 in. dia., bears N10°W 141.5', scribed T15S R26E S28, B.T.
- A Juniper, 9 in. dia., bears N67°E 60.5', scribed T15S R26E S27, B.T.
- A Pond. Pine, 9 in. dia., bears S51°E 136.0', scribed T15S R26E S34, B.T.
- A Pond. Pine, 8 in. dia., bears S55°W 164.1', scribed T15S R26E S33, B.T.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

James R. Tye
**OREGON
JULY 22, 1977
JAMES R. TYE
1104**

Michael Yardley
Witness to Corner: Michael Yardley
Chainman

I hereby certify the above monument was re-established as herein described on 7-11-79.

Office of *Surveyor* County of *Grant*
State of *Oregon*, I hereby certify that the within instrument was filed in this office for record on the *23* day of *Aug*, 19*79*, at *1:30* clock *P* m., (signed)
Robert W. Bess by *Michael Yardley*
(COUNTY OFFICIAL) (DEPUTY)