


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Samuel W. Lackland, Deputy Surveyor, under G.L.O. Contract No. 384 dated March 29, 1881.

Surveyor General's records state:

30.05 Rim rock about 70 ft high N.W.
40.00 Set basalt stone 28X12X8 in mound of stone for 1/4 Sec Cor.



L-25
F.B.2 Pgs.19&20

Description of corner evidence found:

At assumed corner location I made a thorough search for the original corner and found no evidence of original stone nor stone mound. Corner falls on scab rock flat on top of shake table with much surface stone. I determine corner is lost and re-establish by survey.

Description of monument and accessories established to perpetuate the original location of this corner:

At single proportionate position as determined by survey, set 2-1/2 inch O.D. X 30 inches long aluminum pipe 12 inches in ground to bedrock with 3 inch aluminum cap marked as shown:


Marked bearing trees:

An 8" Juniper bears South 82° East, 85.7 ft., scribed-1/4S18BT;
An 8" Juniper bears South 15-1/2° West, 33.3 ft., scribed-1/4S13BT.

Raised stone mound 4 foot diam. to cap. Set steel post 3 feet South with sign 54-4 facing cap. Painted red band and faces red and nailed signs 54-3 and 54-4 to BT's. Nailed brass washer stamped "AS&E LS1026" to face of BT's.

I hereby certify that the above corner monument was re-established as herein described on May 19, 1987.

Witness: David B. Armstrong



M.V.19-1/2°E.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David B. Armstrong

6/24/87 OREGON
AUGUST 22, 1973
DAVID B. ARMSTRONG
1026

Office of... *Surveyor* ... County of... *Grant* ...
State of... *Oregon* ... I hereby certify that the within instrument was filed in this office
for record on the... *19*... day of... *Aug* ... , 19... *87* ...
Robert W. Bayart by ...
(COUNTY OFFICIAL) (DEPUTY)