

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by S. W. Lackland, US Deputy Surveyor, during the original survey Contract No. 384 dated March, 1881.

Set post for 1/4 sec cor with pits & mound from which

A fir 12 ins diam bears N85°E, (9.9') 15 lks dist

DIAGRAM

T15S
R28E R29E

1/4
S36|S31

1986
FLS 699

Description of corner evidence found:

An earth mound with a more recent wood post, but found the outline of the original post in the ground.

24" Douglas-fir (Good Condition) (Blaze Opened by Others) (1881 BT) bears N85°E, 12.5 feet feet.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the diagram, 26" in the ground, at the location of the old post and layed any post remains alongside the monument. Built a mound of earth to be 30" in diameter by 4" high around the monument, from which a new BT is:

12" Douglas-fir bears N62° 30'W, 53.8 feet scribed 1/4 S36 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were taken with a staff compass, using a declination of 18° 30'E, to stamped brass washers nailed in the scribed red-painted blazes.

Distances were measured from a 60d spike, with an aluminum washer stamped FLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet N of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on November 21, 1986, I monumented the corner as herein described.

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 6 DAY OF April, 1987

Robert D. Sigart
Grant County Surveyor

