


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. P-9

History of original corner establishment:

Original survey was by S.W. Lackland under GLO Contract No. 357, dated July 2, 1880.


Set post for 1/4 section corner from which
 a Pine 36" in diameter bears S60°E, 70 lks. dist.
 a Pine 48" in diameter bears S45°E, 76 lks. dist.



Description of corner evidence found:

A diligent search was made and no trace of the corner or accessories could be found. Found location tag on old dead stump, marked Sec. 20 T15S, R30E, 10 ft. N75°E to 1/4 cor. Could find no evidence substantiating the information on the location tag.

Description of monument and accessories established to perpetuate the original location of this corner: At surveyed point:



Set 2½"x30" galvanized pipe with brass cap stamped:

Set pipe 16" in ground with mound of stone to cap.

From which:

A Ponderosa Pine 9" in diameter bears S53°E, 8.0 ft., scribed 1/4 S21 BT.

A Ponderosa Pine 16" in diameter bears N59°W, 56.5 ft., scribed 1/4 S20 BT.

Painted blazes and 6" band around both BTs orange. Attached 54-3 and 54-4 signs to both BTs. Attached brass washer to foot blaze of both BTs. Attached 54-2 and 54-4 signs to metal fence post 5' West of corner. Attached 54-2 sign to fence post 5' North of corner.



I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Rodger Orton
 Glen Wagoner
 Jeff Anderson

July 10, 1979

Office of..... County Surveyor County of. . . Grant.
 Oregon

State of..... I hereby certify that the within instrument was filed in this office
 for record on the.. 4.. day of.. Oct .., 1979

..... Robert D. Bayliss by
 (COUNTY OFFICIAL) (DEPUTY)