


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. R-7

History of original corner establishment:

Original survey was by S. W. Lackland under GLO Contract No. 357, dated July 2, 1880.

Set post for 1/4 section corner with pits and mounds as per instructions.



Description of corner evidence found:

A diligent search was made and no evidence of the corner could be found.

Description of monument and accessories I established to perpetuate the original location of this corner: At surveyed point:

Set 2 1/2" x 30" galvanized pipe with brass cap stamped: Set pipe 22" in ground with mound of stone to cap.


From which:

An Aspen 11" in diameter bears N39°W, 13.3 ft., scribed 1/4 S20 BT.

An Aspen 10" in diameter bears S37°W, 15.25 ft., scribed 1/4 S29 BT.

Painted blazes and 6" band around both BTs orange. Attached 54-3 and 54-4 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Attached 54-2 and 54-4 signs to metal fence post 5 ft. west of corner. Attached 54-2 sign to metal fence post 5 ft. south of corner.

T15S R30E WM
 1/4 S20
 ───┬───
 S29
 1979
 OR PLS 1294



I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Rodger Orton
Glen Wagoner
Jeff Anderson

July 13, 1979

Office of County Surveyor County of Grant
 Oregon I hereby certify that the within instrument was filed in this office
 for record on the 4 day of July 19 79
 by
 (COUNTY OFFICIAL) (DEPUTY)