


CORNER RESTORATION

CORNER: S $\frac{1}{4}$ Sec: 21 TWP: 15S. RANGE: 30E.

ORIGINAL SURVEY BY: S.W. Lackland

CONTRACT NUMBER: 357


CONTRACT DATE: July, 1880



ORIGINAL DESCRIPTION: Set stone 16"x6"x5" in mound of stone for $\frac{1}{4}$ section corner.

RESTORATION BY, STAMP AND DATE:

R.D. Bagett
G.J. Russell
N.I. Fowle
S.D. Follweiler



Robert D. Bagett
OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

RECEIVED AND
FILED

OCT 16 1992

CLERK OF COUNTY SURVEYOR
Robert D. Bagett
Attest: *J.P. [Signature]*

Sept. 29, 1992

EVIDENCE FOUND: No evidence of the original corner stone or the mound of stone was found. Set by survey, at single proportionate measure between the found monuments at the Southwest and Southeast corners of section 21. From the corner point:
A fence corner running North, South, East, and West bears S76°E., 46.4 ft.

See Record Map of Survey No.1226.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: I set a 2 $\frac{1}{2}$ "x30" galv. iron pipe, 32" in the ground, with attached Brass Cap marked as shown.

From which I SET NEW REFERENCES POINTS:

A 5/8"x30" iron pin, bears N48°E, 65.0 ft., with attached alum. cap marked BGA SURVEY MARKER RP1 1992 OPLS598.
A 5/8"x30" iron pin, bears S42°E, 12.9 ft., with attached alum. cap marked BGA SURVEY MARKER RP2 1992 OPLS598.
A 5/8"x30" iron pin, bears S48°W, 12.0 ft., with attached alum. cap marked BGA SURVEY MARKER RP3 1992 OPLS598.
A 5/8"x30" iron pin, bears N42°W, 25.0 ft., with attached alum. cap marked BGA SURVEY MARKER RP4 1992 OPLS598.

BAGETT-GRIFFITH
AND ASSOC.

T15S R30E
S21
 $\frac{1}{4}$ ———
S28
1992
OPLS 598

Buried brass cap 2" below surface of ground. Raised mound of stone 2 ft. base around cap. Used mag. compass with 20°E var. and a steel tape.