


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Corner not previously established.



T-22
F.B. 7 P. 49,50

Description of corner evidence found:

None. Corner not previously established.

Description of monument and accessories | established to perpetuate the original location of this corner:

At position as determined by survey set a 2-1/2"O.D.x30" long aluminum pipe 27" in ground with a 2-1/2" diameter aluminum cap marked as shown: No stone available for mound.

Marked bearing trees:

A 10" Ponderosa Pine bears South 44-1/2° East, 56.0 ft., scribed "CW1/16S25BT"; an 18" Ponderosa Pine bears South 54° West, 181.6 ft., scribed "CW1/16S25BT". Painted a 6" red band and face blazes red. Nailed signs 54-9 and 54-3 to BT'S. Nailed a brass washer stamped "LS 1026" to face blazes of BT'S. Set a steel fence post 5ft. North of cap with signs 54-9 and 54-2. Bearings are by staff compass and declination is 19-1/2° East.

I hereby certify that the above corner monument was re-established as herein described on October 23, 1989.

Witnesses: Wes G. Heigh
Paul D. Woodworth

See C.S. #1121

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David B. Armstrong

12/12/89 OREGON
AUGUST 22, 1975
DAVID B. ARMSTRONG
1026

Office of Surveyor County of Grant
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 13 day of Feb, 1990
Robert H. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)