


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Corner not previously established.



V-22
F.B. 9 P. 72,73

Description of corner evidence found:
None. Corner not previously established.

Description of monument and accessories established to perpetuate the original location of this corner:

At position as determined by survey set a 2-1/2"O.D.x30" long aluminum pipe 24" in ground with a 2-1/2" diameter aluminum cap marked as shown: Raised a 3 ft. diameter stone mound to cap.

RM's Set:

A 1"x24" long iron rod bears North 29° East, 21.33 ft., stamped "RM S25 LS1026 1989"; a 1"x24" long iron rod bears South 64-1/4° East, 28.55 ft., stamped "RM S36 LS1026 1989". Set a steel post 1 ft. past RM's on line with cap with sign 54-9 facing RM's. Set a steel post 5 ft. North of cap with signs 54-2 and 54-9. Bearings are by staff compass and declination is 19-1/2° East.

I hereby certify that the above corner monument was re-established as herein described on October 25, 1989.

Witnesses: Wes G. Heigh
Paul D. Woodworth

See C.S. #1121

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David B. Armstrong

12/12/89 OREGON
AUGUST 21, 1975
DAVID B. ARMSTRONG
1026

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 13 day of Feb, 1990
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)