


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Standard Corner



**History of original corner establishment:**

Corner originally established by S. W. Lackland, under joint contract #357, dated July 2, 1880.

Surveyor General's records state: Set post from which; a pine 25" in diameter bears N 37°E 24 links distance a pine 18" in diameter bears N 30°W 50 links distance

**Description of corner evidence found:**

Found no evidence of original post.

Found stump hole northeast but no evidence of bearing tree.

Found stump 19" in diameter with burnt face. Visible scribing, but unreadable. Bench mark on back of stump. N 30°W 50 links distance.

**Description of monument and accessories | established to perpetuate the original location of this corner:**

At record bearing and distance from northwest bearing tree; I set a 2½"x30" aluminum pipe with a ¾" aluminum cap, 25" in ground. Cap marked;

**Bearing trees**

a ponderosa pine 15" in diameter bears N 54°W 32.2 feet distance, scribed "T15SR30ES31SC" in upper blaze and "BT" and brass tag stamped RLS 1664 in lower blaze.

a ponderosa pine 11" in diameter bears N 04°E 108.0 feet distance, scribed "T15SR30ES32SC" in upper blaze and "BT" and brass tag stamped RLS 1664 in lower blaze.


Compass declination 18° East

**Note**

I set a steel fence post with USFS Attention sign at corner, placed USFS bearing tree signs on all bearing trees, and painted red band on smooth bark at breast height on all bearing trees.

I hereby certify the above corner location was perpetuated as herein described on June 19, 1981.

Terry Butler Terry Butler, Witness



REGISTERED PROFESSIONAL LAND SURVEYOR

Carl E. Sundet  
OREGON  
JULY 14, 1978  
CARL E. SUNDET  
1664

Office of Surveyors County of Grant  
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 23 day of Oct, 1981  
Robert D. Slight by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)