

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. C-22

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T15S R31E
W1/16
C-.-C
S 1
1988
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 28" in the ground.
From Which:
A Fine 14" dia., Bears S75°E., 39.0 ft., scribed: CW 1/16 S1 BT
A Fine 10" dia., Bears N24°W., 47.3 ft., scribed: CW 1/16 S1 BT
Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.
Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, 3 ft. North & West from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1988
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: March 22, 1988
Refer to Map of Survey No. 1034

Office of Surveyor County of Grant
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 28 day of Mar, 1988
Robert D. Lopez by _____
(COUNTY OFFICIAL) (DEPUTY)