

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. G-23

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T15S R31E
C1/4
S12
1988
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 12" in the ground and raised a mound of stone around the pipe.

From Which:

A Mahogany 6" dia., Bears N44°W., 31.4 ft., scribed: X BT

A Pine 12" dia., Bears S17°E., 21.8 ft., scribed: C1/4 S12 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast hl. around each tree. Set steel fence post with warning Sign, in the stone mound around the pipe, North alongside the pipe.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1893
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: March 31, 1988
Refer to Map of Survey No. 1034

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 28 day of Mar, 1989
Robert D. Beggs by _____
(COUNTY OFFICIAL) (DEPUTY)