

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. L-17

History of original corner establishment:

Corner was originally established by Bamford Robb, in July 1880, under General Land Office Contract No. 357. The U.S. Surveyor General's Notes State: Set basalt stone 12x6x5 in mound of stone for 1/4 sec. cor.

DIAGRAM

T15S R31E
1/4
S151S14
1988
RLS 848

Description of corner evidence found:

After searching over a wide area and defining a small search area, no evidence is found. There is no particular reason why this corner should not be in place.

There are no accessories originally established. R.D. Baggett searched for this corner in 1986, See Map of survey No 956.

Reestablished corner position at proportionate measure between the Section corner as set from proportionate measure as a portion of this survey, 1/2 mi. North & and the Section Corner found 1/2 mi. South.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 26" in the ground.

From Which:

A Juniper 16" dia., Bears S51°E., 75.1 ft., scribed: 1/4 S14 BT

A Juniper 14" dia., Bears S83°W., 96.8 ft., scribed: 1/4 S15 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence post with warning Sign, alongside the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1953
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: April 28, 1988
Refer to Map of Survey No. 1038

Office of Sumner County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 28 day of Mar, 1989
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)