

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. L-19

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T15S R31E
C1/4
S14
1988
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 18" in the ground and raised a mound of stone around the pipe.

From Which:

Set 5/8"x30" iron pin with plastic cap stamped PLS 848 & guard posts with warning and bearing tree signs, North 10.0 ft. and South 10.0 ft. from the corner.

Measurements to pins taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1958
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: April 19, 1988
Refer to Map of Survey No. 1038

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*..... I hereby certify that the within instrument was filed in this office
for record on the.....*28*..... day of.....*Mar*....., 19.....*89*.....
.....*Robert D. Begett*..... by.....
(COUNTY OFFICIAL) (DEPUTY)