


CORNER RESTORATION

W. $\frac{1}{4}$ cor.
CORNER Sec. 13 TWP 15 S. RANGE 31 E.

ORIGINAL SURVEY BY: Banford Robb

CONTRACT NUMBER: 357

CONTRACT DATE: July 2, 1880



ORIGINAL DESCRIPTION:

40.00 - Set basalt stone 12"x8"x6" in mound of stone for the $\frac{1}{4}$ section corner from which,

A fir 12 in. dia. bears S36°W., 38 Lks. dist.

A fir 30 in. dia. bears N 8°E., 34 Lks. dist.

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett
OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

September 27, 1972

EVIDENCE FOUND: NONE.

Set West $\frac{1}{4}$ section corner by proportionate measurement.

See Survey No. 274.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 1 $\frac{1}{2}$ "x30" galvanized iron pipe 20" in the ground with Brass Cap marked as shown, from which NEW BEARING TREES,

MONUMENT MARKED

A 13" fir bears S10°32'E, 81.60 to nail, marked
 $\frac{1}{4}$ S.13 C.S. B.T. Nail set in base of blaze.

An 8" fir bears N67°15'W., 54.40 feet to nail,
marked $\frac{1}{4}$ S.14 C.S. B.T. Nail set in base of blaze.

Surrounded pipe with mound of stone.

It falls in road cut slope on south side of road
Complete and File with Office of the Grant

County Surveyor, Grant County, Oregon, Comp. Var. 20°
Courthouse, Canyon City, Oregon 97820

