


CORNER RESTORATION

Center $\frac{1}{4}$ cor.
CORNER Sec. 13 TWP 15 S. RANGE 31 E.

ORIGINAL SURVEY BY:

CONTRACT NUMBER:

CONTRACT DATE:



ORIGINAL DESCRIPTION:

No original description.

RECEIVED AND
FILED

OCT 18 1972

John Liveira
JOHN LIVEIRA, County Clerk

RESTORATION BY, STAMP AND DATE:

By _____ Deputy

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

Sept. 28, 1972

EVIDENCE FOUND:

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings, including compass var.
Set $5/8$ "x30" iron pin and plastic cap marked B-G-F survey MK,
From which NEW BEARING TREES,

MONUMENT MARKED

A 14" pine bears S26°43'E., 19.80 feet marked
C $\frac{1}{4}$ CS BT

A 16" pine bears S82°07'E., 62.90 feet marked
C $\frac{1}{4}$ CS BT

Measurements to nails at base of B.T's



Complete and File with Office of the Grant Comp. Var. 20°
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820