

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. C

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

PV1
USFS
1988
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

At the position as determined from Bool. 77, Page 263 of the Grant County Deed Records, set a monument marking the boundary of USFS land.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 20" in the ground.

From Which:

A Fir 10" dia., Bears S78°E., 29.2 ft., scribed: Bdry Cor BT

A Fir 11" dia., Bears S81°W., 6.0 ft., scribed: Bdry Cor BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. No Point used in the close proximity to a private home. Set steel fence posts with warning & Boundary Signs, on property line 5 ft. each way from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1999
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: April 29, 1988
Refer to Map of Survey No. 1038

Office of.....*Oregon Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*28* day of.....*Mar*....., 19.....*89*
.....*Robert H. Baggett*..... by.....
(COUNTY OFFICIAL) (DEPUTY)