

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. E

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

IPVT
--
USFS
1988
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

At position of corner as determined from Book 117, Page 940, as derived from Book 83, Page 439 of the Grant County Deed Records, set a monument marking boundary of USFS land.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 24" in the ground.

From Which:

A Fir 8" dia., Bears S 80°18'E., 32.8 ft., scribed: Bdry Cor BT

A Fir 12" dia., Bears S 51°07'W., 43.8 ft., scribed: Bdry Cor BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, S 80°28'E & N 8°22'E., 3 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1953
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: May 2, 1988
Refer to Map of Survey No. 1038

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 28 day of Mar, 1989
Robert D. Beyer by _____
(COUNTY OFFICIAL) (DEPUTY)