


CORNER RESTORATION

S.E. Cor.
CORNER Sec. 13 TWP 15 S. RANGE 31 E.

ORIGINAL SURVEY BY: Banford Robb

CONTRACT NUMBER: 357

CONTRACT DATE: July 2, 1880



ORIGINAL DESCRIPTION:

80.00-set stone 18"x10"x6" for corner to sections 13, 24, 18 & 19

From which,

A pine 30" dia. bears N45°W, 16 Lks.

A pine 20" dia. bears N70°E, 59 Lks.

A pine 30" dia. bears S20°E, 31 Lks.

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

RECEIVED AND
FILED

OCT 16 1972
JOHN LIVEIRA, County Clerk

By _____ Deputy

ROBERT D. BAGETT
JULY 12, 1963
598

Sept. 23, 1972

EVIDENCE FOUND:

Original Bearing tree, a live 38" pine marked S. 19 T.15 R. B.T.
with forest service cruise tag attached.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 1½"x30" galv. iron pipe 24" in ground at Record bearing and distance
from original B.T. with brass cap marked as shown. MONUMENT MARKED
From which NEW BEARING TREES,

A 15" pine bears N76°E, 68.7 feet marked T15S, R32E S18
C.S. B.T.

A 12" pine bears S79°W, 24.4 feet marked T15S, R31E S24
C.S. B.T.

A 15" pine bears N90°W, 13.8 ft marked T15S, R31E, S13
O.S. B.T.

Measured horizontal distances to blaze on B.T.s from
brass cap

Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon, Comp Var. 20°
Courthouse, Canyon City, Oregon 97820

