

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. P-21

History of original corner establishment:

Corner was originally established by
Bamford Robb, in July, 1880, under
General Land Office Contract No. 357.
The U.S. Surveyor Generals Notes State:
Set Basalt stone 14x8x6, in mound of
stone for 1/4 sec. cor.

DIAGRAM

R15S R31E
1/4
S231S24
1988
RLS 848

Description of corner evidence found:

Corner falls on a very steep, open South slope.
There are no stones of call size in the area, or any
trace of a man made stone mound.

There are no accessories originally established.
Corner is lost to erosion on this steep slope.
Reestablished the corner position at proportionate
measure between the section corners found 1/2 mi.
North and South.

**Description of monument and accessories established to perpetuate the
original location of this corner:**

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown
on the **DIAGRAM**, SET 8" in the ground and raised a mound of earth & stone
around the pipe.

From Which:

Set 5/8"x30" iron pins with plastic caps marked SURVEY MARKER PLS 848, and
guard posts with Bearing Tree and warning signs East 10.0 ft. and West 10.0 ft
from the corner.

Measurements to pins taken with a metal tape and magnetic compass,
with Declination set off 20 deg. East.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1939
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: April 1, 1988
Refer to Map of Survey No. 1034

Office of Surveyor County of Grant
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 28 day of May, 1989
Robert D. Sapp by _____
(COUNTY OFFICIAL) (DEPUTY)