

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. P-23

**History of original corner establishment:**

Grant County Survey Records show no previous establishment of this Cor.

**DIAGRAM**

T15S R31E  
C1/4  
S24  
J988  
RLS 848

**Description of corner evidence found:**

Grant County Survey Records show no previous establishment of this Cor.

**Description of monument and accessories | established to perpetuate the original location of this corner:**

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 10" in the ground and raised a mound of earth and stone around the pipe.

From Which:

Set 1/2"x30" iron pins with plastic caps marked SURVEY MARKER PLS 848, and guard posts with Bearing tree and warning signs North 10.0 ft. and West 10.0 ft from the corner.

Measurements to pins taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 12, 1933  
DOUGLAS M. FERGUSON  
848

This work is performed by:  
Douglas M. Ferguson RLS 848  
Mt. Vernon Oregon.  
On: April 1, 1988  
Refer to Map of Survey No. 1034

Office of Surveyor County of Grant  
State of Oregon, I hereby certify that the within instrument was filed in this office  
for record on the 28 day of Mar, 1989  
Robert D. Boyer by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)