

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. T-1

**History of original corner establishment:**

Corner was originally established by  
Samual W. Lackland, in July. 1880,  
under General Land Office Contract  
No. 357.  
The U.S. Surveyor Generals Notes State:  
Set post for 1/4 Sec. cor.

**DIAGRAM**

T15S  
R30E R31E  
1/4  
S251S30  
1986  
RLS 848

from which

A Pine 20 in dia. bears S10<sup>0</sup>W, 40 lks dist.  
" " 18 " " " N10<sup>0</sup>E, 20 lks dist.

**Description of corner evidence found:**

No trace of the original post is found.

Bearing Trees have been lost to logging.  
Established corner at proportionate measure between  
corners found 1/2 mi. North and South.

**Description of monument and accessories | established to perpetuate the  
original location of this corner:**

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown  
on the DIAGRAM, SET 22" in the ground.

From Which:

A Pine 16" dia., Bears N41<sup>0</sup>W., 30.4 ft., scribed: 1/4 S25 BT

A Pine 14" dia., Bears N13<sup>0</sup>E., 34.1 ft., scribed: 1/4 S30 BT

Measurements to trees taken with a metal tape and magnetic compass,  
with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing  
Tree Sign above blaze, and warning sign on back of each tree. Painted  
a 6" red band at breast ht. around each tree. Set steel fence post with  
warning Sign, North 4 ft. from the corner.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 12, 1993  
DOUGLAS M. FERGUSON  
848

This work is performed by:  
Douglas M. Ferguson RLS 848  
Mt. Vernon Oregon.  
On: Dec. 18, 1986  
Refer to Map of Survey No. 977

Office of.....*Surveyor*..... County of.....*Grant*.....  
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office  
for record on the.....*30*..... day of.....*April*....., 19.....*87*.....  
.....*Robert L. Baggett*..... by .....  
(COUNTY OFFICIAL) (DEPUTY)