

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. T-7

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T15S R31E
C1/4
S29
1987
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 26" in the ground.
From Which:
A Fir 12" dia., Bears N 5⁰E., 28.7 ft., scribed: C1/4 S29 BT
A Fir 12" dia., Bears S51⁰W., 11.3 ft., scribed: C1/4 S29 BT
Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.
Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence post with warning Sign, North 3 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1989
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: April 14, 1987
Refer to Map of Survey No. 991

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 24 day of July, 1987
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)