


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. V-2

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.



Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:



Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 24" in the ground.

From Which:

Set 5/8" iron pins with plastic caps stamped SURVEY MARKER PLS 848 and guard posts with warning and Bearing tree signs, as follows:

N89°41'W., 38.9 ft., on West side of road approach, and South 10.8 ft. from the corner.

Measurements to pins taken with a Electronic Tacheometer with angles turned from the survey control network.



This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Dec. 12, 1986
Refer to Map of Survey No. 974

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 30 day of April, 1987
Robert O. Boyett by _____
(COUNTY OFFICIAL) (DEPUTY)