


CORNER RESTORATION

W ¼ corner
CORNER Sec. 31 TWP 15 S RANGE 31E
ORIGINAL SURVEY BY: S. W. Lackland
CONTRACT NUMBER: 357
CONTRACT DATE: July 2, 1880




ORIGINAL DESCRIPTION:

40.00 set post for ¼ section corner with pits and mounds as per instructions

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
W. A. Potridge



July 8, 1981

RECEIVED AND
FILED

AUG 11 1981

OFFICE OF COUNTY SURVEYOR
Robert D. Bagett
Attest: *Carol A. ...*
Co. clerk

Grant County Surveyor

EVIDENCE FOUND:

I did not find the original ¼ corner post or any acceptable evidence of its position. After a diligent search with no luck, I established, by survey, the ¼ corner at single proportionate measure between the NW corner and the SW corner of Section 31.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:
Show how trees are scribed and basis of bearings, including compass var.

At the corner point:
Set a 1½"x30" galvanized iron pipe 28 inches in the ground with a brass cap marked as shown.

No bearing trees or bearing objects available.

This corner falls within 5 ft. of the intersection of old fence lines which have been removed. Post holes are about all that remain.

This corner is on a sage brush knoll.

MONUMENT MARKED

