

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. 7-2

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T15S R31E
W1/16 S31
-.-
1986
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories, established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 20" in the ground.

From Which:

A Pine 8" dia., Bears N34°W., 15.1 ft., scribed: W1/16 S31 BT

A Pine 8" dia., Bears N 6°E., 7.5 ft., scribed: W1/16 S31 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence post with warning Sign, East 5 ft. from the corner.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

**OREGON
JULY 12, 1969
DOUGLAS M. FERGUSON
848**

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Dec. 12, 1986
Refer to Map of Survey No. 974

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 30 day of April, 1987
Douglas M. Ferguson
(COUNTY OFFICIAL) (DEPUTY)