


CORNER RESTORATION

SW cor.
CORNER Sec. 34 TWP 15 S. RANGE 31 E.

ORIGINAL SURVEY BY: A. O. Ecelson

CONTRACT NUMBER: 328

CONTRACT DATE: June 20, 1879



ORIGINAL DESCRIPTION:

East on South boundary of Section 33.
Set post for corner to Sections 33 and 34
from which

A Pine 18 ins. diam. bears N. 40° W., 69 lks. dist.

A Pine 30 ins. diam. bears N. 28° E., 57 lks. dist.

RECEIVED AND
FILED

JUN 20 1986

OFFICE OF COUNTY SURVEYOR

Robert D. Baggett
Attest: *M. D. Baggett*

RESTORATION BY, STAMP AND DATE:

R. D. Baggett

M. D. Baggett

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1963
ROBERT D. BAGGETT
598

May 10, 1986

Grant County Surveyor

EVIDENCE FOUND:

Decaying remains of 8x4x4 inch original wood post, the top of which was
12 ins. below ground - clearly sharpened with an axe, from which:

A P. Pine, alive & well, 35 ins. diam. bears N. 40° E., 38.3 feet
scribing visible in partially healed upper blaze - marked BT in lower
blaze.

A P. Pine, alive & well, 20 ins. diam. bears N. 22° W., 45.8 feet
marked 31 in upper blaze - lower blaze healed over.

Measured to face of original BT's.

See Record Map of Survey No. 938.


DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the center of the original post, I set a
1½x30 inch galv. iron pipe 28 ins. in the ground.

I do not scribe new trees.

MONUMENT MARKED



Painted 6" red band around new BT's above blaze and on blaze and
attached BT signs and warning signs to BT's. Set steel fence
posts approx. 5 feet North and East from monument and attached
appropriate signs. Used magnetic compass with 19° E. var. and steel
tape measuring to face of original BT's.