

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. W-13

History of original corner establishment:

Corner originally established by W.M.H. Woodward, Mineral Examiner, Sept. & Oct. 1917, Field Notes for that "Homestead Entry Survey No. 217, State: (Abbreviated) Establish Cor. No.3 of this survey and 1/16 sec. cor. as follows: Set sandstone 24x8x8 ins. 14 ins in the ground over chinaware (marked as shown in said notes) Took 2 Bearing trees, See said notes.

DIAGRAM

T15S R32E
N1/16
S331S34
HES 217
COR NO3
1987
RLS 848

In 1976 R.D. Bagett PLS 598 reestablished this corner at midpoint between the the section corner and the 1/4 corner, as called for on the CORNER RESTORATION sheet, as referenced to Map of Survey No. 398 of the Grant County Survey Records. That sheet states:
At the corner point: Set a 5/8"x30" iron pin 26" in the ground, from which:
ORIGINAL BT: a 36" pine bears N10°W., 27.0 ft. mkd. X3HES217 BT
I scribe NEW BT: A 6" fir bears N68°E., 19.6 ft. mkd. N1/16S34CSBT

Description of corner evidence found: even in the ground.

Found original Bearing Tree and Tree as scribed by PLS 598, See CORNER RESTORATION sheet as referenced to Map of survey No. 398 of the Grant County Survey Records.

Accepted the 5/8" iron pin as reestablished 1/16 cor and cor. No.3 as reestablished at midpoint between the Section Corner and the 1/4 Corner as called for on that Map of Survey No. 398.

Description of monument and accessories | established to perpetuate the

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, Set 27" in the ground.

From Which: (NEW BEARING TREES)

A Fir 12" dia., Bears N 10°W., 8.4 ft., scribed: N1/16 S33 HES COR 3 BT
A Fir 10" dia., Bears S 70°W., 33.0 ft., scribed: N1/16 S34 HES COR 3 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, N56°W., 3 ft. & South 3 ft., from corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1969
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: April 2, 1987
Refer to Map of Survey No. 990

Office of.....*Sumner*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*29* day of.....*May*....., 19..*87*
.....*Robert D. Bagett*..... by.....
(COUNTY OFFICIAL) (DEPUTY)