

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. HES 217 COR No.7

History of original corner establishment:

Corner originally established by W.M.H. Woodward, Mineral Examiner, Sept. & Oct. 1917, Field Notes for that "Homestead Entry Survey No. 217, State: Set a sandstone, 24x12x10 ins., 6 ins. in the ground on solid bedrock, in a mound of stone, over broken glass, for cor. No.7 of this survey, marked with a cross (X) on top for exact cor. point and 7 HES 217 on side facing claim, from which:

A pine 36 ins. dia., bears S51°15'E., 75 lks. dist. marked X7 HES 217 BT
A pine 4 ins. dia., bears S66°15'W., 41 lks. dist. marked X7 HES 217 BT
In 1976 R.D. Baggett PLS 598 found this corner and re-monumented.

The "CORNER RESTORATION" sheet as filed with Map of Survey No. 398 States:
At the corner point and under "X" on original HES cor. stone I set a 5/8"x30" iron pin, 30" in ground and replaced original corner stone over top of pin.
I scribe NEW BT:

A 7" in diam. juniper brs. S. 31°E., 31.6 ft., dist. mkd. HES7CSBT

Description of corner evidence found:

Made a search, the pin is not found, computed position and found a 5/8" iron pin driven below the surface of the ground, under a rock jack.

Fencing has displaced the original stone.

Found 20" Pine with blaze scar on proper face, Bears S66°W., 27.3 ft.

Found 40" Pine stump scribed X7 HES, Bears S51°E., 48.5 ft.

Found 7" Juniper scribed HES 7 CS BT, Bears S31°E., 31.6 ft.

Remonumented the 5/8" iron pin, as shown below.

DIAGRAM

T15S R32E
HES 217
COR NO.7
1987
RLS 848

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 26" in the ground.

From Which: (New Bearing Trees)

A Pine 12" dia., Bears S77°W., 37.9 ft., scribed: HES 217 COR 7 BT

A Pine 12" dia., Bears S81°E., 45.2 ft., scribed: HES 217 COR 7 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, S56°E., 5 ft., and N80°W., 5 ft. from the corner.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: April 1, 1987
Refer to Map of Survey No. 990

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*29*..... day of.....*May*....., 19.....*87*.....
Robert H. Baggett by.....
(COUNTY OFFICIAL) (DEPUTY)