

# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. J-7 LINE TREE

## History of original corner establishment:

Corner was originally established by  
Samual W. Lackland, in 1881.  
under General Land Office Contract  
No. 384.  
The U.S. Surveyor Generals Notes State:  
31.36 Ch. Fir 36 in. dia.  
39.76 (Set 1/4 Cor.)

## DIAGRAM

T15S R32E  
LINE TREE  
S8  
-.-  
S17  
1987  
RLS 848

## Description of corner evidence found:

Found down and rotten Fir, approx. 46" dia., with  
bark blaze on East face. West face has rotted away.  
This is the only large Fir tree in the area. this slope  
is predominantly Pine. Accepted as the original tree.

## Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown  
on the **DIAGRAM**. SET 27" in the ground at center of root hole.  
From Which:  
A Pine 10" dia.. Bears N11°W.. 12.7 ft., scribed: LINE TREE S8 BT  
A Pine 8" dia.. Bears S29°W.. 17.0 ft., scribed: LINE TREE S17 BT  
Measurements to trees taken with a metal tape and magnetic compass.  
with Declination set off 20 deg. East.  
Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing  
tree sign above blaze, and warning sign on back of each tree. Painted  
a 6" red band at breast ht. around each tree. Set steel fence post with  
warning sign, North 3 ft. from pipe.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 12, 1960  
DOUGLAS M. FERGUSON  
848

This work is performed by:  
Douglas M. Ferguson RLS 848  
Mt. Vernon Oregon.  
On: Sept. 2, 1987  
Refer to Map of Survey No. 1016

Office of.....*Surveyor*..... County of.....*Grant*.....  
State of.....*Oregon*..... I hereby certify that the within instrument was filed in this office  
for record on the.....*7*..... day of.....*May*....., 19.....*88*  
.....*Robert D. Bayart*..... by .....  
(COUNTY OFFICIAL) (DEPUTY)