

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. L-3

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T15S R32E
C1/4
S18
J987
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 8" in the ground and raised a mound of stone around the pipe.

From Which:

A Juniper 12" dia., Bears S83°W., 17.2 ft., scribed: C1/4 S18 BT

A Pine 12" dia., Bears S24°E., 49.1 ft., scribed: C1/4 S18 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence post with warning sign, North 3 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Nov. 10, 1987
Refer to Map of Survey No. 1021

Office of... *Surveyor* County of... *Grant*
State of... *Oregon* I hereby certify that the within instrument was filed in this office
for record on the... *28* day of... *Nov* 19*87*
Robert D. Beyer by
(COUNTY OFFICIAL) (DEPUTY)