

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. L-6

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

R158 R32E
W1/16
C--C
S17
1987
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap. stamped as shown on the **DIAGRAM**. SET 3" in the ground and raised a mound of stone around the pipe.

From Which:

A Juniper 8" dia., Bears N14°E., 95.9 ft., scribed: C-W 1/16 S17 BT

A Juniper 12" dia., Bears S59°E., 86.0 ft., scribed: C-W 1/16 S17 BT

Measurements to trees taken with a metal tape and magnetic compass. with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, South 0.5 ft. and West 1.0 ft. from corner, in the above described mound of stone.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1960
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Oct. 2, 1987
Refer to Map of Survey No. 1016

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 7 day of May, 1988
Court D. D. D. by _____
(COUNTY OFFICIAL) (DEPUTY)