

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. L-7

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T13S R32E
C1/4
S17
1987
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 26" in the ground and placed a ring of stone around the pipe.

From Which:

A Pine 7" dia.. Bears N54°W.. 63.4 ft.. scribed: C1/4 S17 BT

A Pine 14" dia.. Bears N69°E.. 23.6 ft.. scribed: C1/4 S17 BT

Measurements to trees taken with a metal tape and magnetic compass. with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence post with warning Sign, North 3 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1953
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Oct. 8, 1987
Refer to Map of Survey No. 1016

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*1*..... day of.....*May*....., 198*8*.....
.....*Roger D. Baggett*..... by
(COUNTY OFFICIAL) (DEPUTY)