

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. M-4

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T15S R32E
SE 1/16
S18
1987
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SE1 10" in the ground and raised a 4'x1-1/2' mound of stone around the pipe.

From Which:

A Pine 12" dia., Bears N31°E., 44.0 ft., scribed: SE 1/16 S18 BT

A Pine 8" dia., Bears S12°E., 36.3 ft., scribed: SE 1/16 S18 Rf

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing tree sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, South & East 1 ft. from the corner in the above described mound of stone.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1960
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Nov. 4, 1987
Refer to Map of Survey No. 1021

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*28*..... day of.....*Mar*....., 19*89*
.....*Robert D. Enright*..... by
(COUNTY OFFICIAL) (DEPUTY)