

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. M-5

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

**DIAGRAM**

T158 R32E  
S1/16  
S18/S17  
1987  
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 4" in the ground and raised a mound of stone & earth around the pipe.

From Which:

A Pine 16" dia., Bears N74°E., 74.1 ft., scribed: S1/16 S17 BT

A Pine 12" dia., Bears S59°W., 31.0 ft., scribed: S1/16 S18 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, North and West of pipe in the above described mound of stone.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 12, 1903  
DOUGLAS M. FERGUSON  
848

This work is performed by:  
Douglas M. Ferguson RLS 848  
Mt. Vernon Oregon.  
On: Oct. 5, 1987  
Refer to Map of Survey No. 1016

Office of Surveyor County of Grant  
State of Oregon, I hereby certify that the within instrument was filed in this office  
for record on the 7 day of May, 1988  
Douglas M. Ferguson by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)