

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. N-2

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T155 R32E
S18
W1/16-.-
S19
1987
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 18" in the ground and raised a small mound of stone around the pipe.

From Which:

A Pine 10" dia., Bears S84°W., 53.4 ft., scribed: W1/16 S19 BT

A Pine 10" dia., Bears N57°W., 41.2 ft., scribed: W1/16 S18 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 4" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, South & West 3 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1960
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Oct. 27, 1987
Refer to Map of Survey No. 1021

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 28 day of Mar, 1989
Robert D. Boyer by _____
(COUNTY OFFICIAL) (DEPUTY)