


CORNER RESTORATION

N.E. Cor.
CORNER Sec. 19 TWP 15S RANGE 32E

ORIGINAL SURVEY BY: Samuel Lackland

CONTRACT NUMBER: 384

CONTRACT DATE: March 29, 1881




ORIGINAL DESCRIPTION:

80.00 set stone 18"x10"x7" in a mound of stone for corn. to Secs. 17, 18, 19 and 20.

RECEIVED AND
FILED

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
W. Gentis



Robert D. Bagett
OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

DEC 20 1976
John Liveira
JOHN LIVEIRA, County Clerk
By _____ Deputy

May 6, 1976

Grant County Surveyor

EVIDENCE FOUND:

At the corner point: Found dimly mkd. stone 18"x10"x7" set in a mound of large stone.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set 1½"x30" iron pipe 14" in the ground surrounded with large mound of stone to top of pipe, with brass cap attached and marked as shown. Buried original stone West and alongside, from which I scribe NEW BT's:

An 18" in diam. pine brs. S. 78° W. 44.6 ft. dist.
mkd. T15SR32ES19CSBT.

A 22" in diam. pine brs. N. 37° W. 54.2 ft. dist.
mkd. T15SR32ES18CSBT.

No trees available in N.E. and S.E. quadrant corner is on West edge of meadow and on remains of old North-South fenceline. I used a compass with 20° East variation and a steep tape, measuring to face of BT blaze.

MONUMENT MARKED

