

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. 0-2

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T15S R32E
NW 1/16
S19
J987
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 28" in the ground.

From Which:

A Pine 14" dia., Bears N36°28'E., 295.3 ft., scribed: NW 1/16 S19 BT

A Pine 16" dia., Bears N75°01'E., 305.6 ft., scribed: NW 1/16 S19 BT

Measurements to trees taken with an electronic tachimeter with angles turned from the survey control network.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, North & East from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1988
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Nov. 3, 1987
Refer to Map of Survey No. 1021

Office of Surveyor County of Grant
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 28 day of Mar, 1987
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)