

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. 0-3

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T15S R32E
C
N1/16S19
C
1987
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 26" in the ground and placed a ring of stone around the pipe.

From Which:

A Pine 14" dia. Bears S11⁰E., 43.4 ft., scribed: CN 1/16 S19 BT

A Pine 8" dia. Bears S82⁰W., 42.3 ft., scribed: CN 1/16 S19 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, North & West 3 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1963
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Nov. 3, 1987
Refer to Map of Survey No. 1021

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*..... I hereby certify that the within instrument was filed in this office
for record on the.....*28*..... day of.....*Mar*....., 19.....*87*
.....*Robert D. Lopez*..... by.....
(COUNTY OFFICIAL) (DEPUTY)