

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. F-3

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM



T15S R32E
C1/4
S19
1987
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 27" in the ground.
From Which:
A Pine 20" dia., Bears S34°E., 28.5 ft., scribed: C1/4 S19 BT
A Pine 18" dia., Bears N48°W., 33.0 ft., scribed: C1/4 S19 BT
Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.
Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence post with warning Sign, North 2 ft. from the corner.



This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Nov. 6, 1987
Refer to Map of Survey No. 1021

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 28 day of Mar, 1987
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)