

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. P-5

History of original corner establishment:

Corner was originally established by Samuel W. Lackland, in 1881, under General Land Office Contract No. 384. The U.S. Surveyor General's Notes State: Set stone 10x8x5 in mound of stone for 1/4 sec. cor.

DIAGRAM

T159 R32E
1/4
S191S20
1987
RLS 848

from which:

A pine 40 in. dia. bears S10°E.. 152 lks dist.

In the 1909 subdivision of this section 20, County Surveyor, Michael Spears found this corner and it was used as a basis of that subdivision.

Description of corner evidence found:

Corner falls in a cultivated field, examined all the stones in the area and did not identify the original stone.

The original Bearing Tree has been grubbed out long ago and there is no trace remaining. Established the corner position at proportionate measure between the N1/16 S19/S20 as properly established by Michael Spears 1/4 mi. North and the original Line Tree, as found 615.51 ft. South.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 26" in the ground.

From Which:

Set 5/8"x30" iron pins with plastic caps stamped SURVEY MARKER PLS 848 and guard posts with with Bearing Tree, Warning and signs, as follows: East 30.0 ft. & West 30.0 ft. from the corner.

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1988
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Oct. 9, 1987
Refer to Map of Survey No. 1016

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*May*..... day of.....*1988*....., 19.....
.....*Robert D. Smith*..... by.....
(COUNTY OFFICIAL) (DEPUTY)