

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. P-7

History of original corner establishment:

Corner position was established by Michael Spears, in Aug. of 1909, however the offsets as computed by Spears from random to true are not correct and he did not permanently mark the corner on the ground.

DIAGRAM

T15S R32E
C1/4
S20
1987
RLS 848

Description of corner evidence found:

No Monumentation of this corner has previously been made.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 23" in the ground.

From Which:

Set 5/8"x30" iron pins with plastic caps stamped SURVEY MARKER PLS 848 and guard posts with with Bearing Tree. Warning and signs, as follows:
North 3.0 ft. & West 3.0 ft. from the corner.

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1909
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Oct. 5, 1987
Refer to Map of Survey No. 1016

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 7 day of May, 1988
Robert H. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)