

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. P-8

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T15S R32E
E1/16
C--C
S20
1987
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 28" in the ground.
From Which:
Set 5/8"x30" iron pins with plastic caps stamped SURVEY MARKER PLS 848 and guard posts with with Bearing Tree, Warning and Boundary signs, as follows:
N00°16'E., 10.0 ft. & N89°57'E., 10.0 ft.
Measurements to pins taken with an Electronic Tacheometer, with angles turned from the survey control network.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1963
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Oct. 5, 1987
Refer to Map of Survey No. 1016

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 7 day of May, 1988
Robert M. Fayth by _____
(COUNTY OFFICIAL) (DEPUTY)