

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. Q-9

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T15S R32E
S1/16
S201S21
1987
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 10" in the ground and raised a mound of stone & earth around the pipe.

From Which:

A Pine 22" dia., Bears N57°W., 7.2 ft., scribed: S1/16 S20 BT
A Juniper 6" dia., Bears S50°E., 27.2 ft., scribed: S1/16 S21 BT
Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.
Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, North & West 4 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1903
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Oct. 7, 1987
Refer to Map of Survey No. 1016

Office of Sumner County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 7 day of May, 1988
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)