


CORNER RESTORATION

NE 1/16
CORNER Sec. 30 TWP 15S RANGE 32E

ORIGINAL SURVEY BY:

CONTRACT NUMBER:

CONTRACT DATE:



ORIGINAL DESCRIPTION:

NE 1/16 Cor. Sec. 30, Not previously established

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
W. Gentis

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

May 24, 1976

Grant County Surveyor

EVIDENCE FOUND:

Not applicable

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.


At the corner point: I drove a 5/8"x30" iron pin 26" in the ground and surrounded same with a mound of stone, from which I scribe NEW BEARING TREES:

MONUMENT MARKED

A 26" fir bears N. 65° W. 39.4 ft. mkd. NE1/16S30CSBT.

A 9" fir bears N. 43° E. 20.8 ft. mkd. NE1/16S30CSBT.

This corner is 20 feet South of an E-W fenceline, and about 35 ft. North of the center of a forest road. I used a compass with a 20° East variation and a steel tape, measuring to the face of the bearing tree blaze.



RECEIVED AND
FILED

DEC 20 1976
John Liveira
JOHN LIVEIRA, County Clerk
By _____ Deputy