


CORNER RESTORATION

C.W. 1/16 Cor.
CORNER Sec. 29 TWP 15S RANGE 32E

ORIGINAL SURVEY BY:

CONTRACT NUMBER: C W 1/16 Cor. Sec. 29, not
previously established.

CONTRACT DATE:




ORIGINAL DESCRIPTION:


C. W. 1/16 Corner not previously established.

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
W. Gentis



Robert D. Bagett



May 4, 1976 Grant County Surveyor

EVIDENCE FOUND:

Not applicable

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 5/8"x30" iron pin for C.W. 1/16 Cor. Sec. 29, from
which I scribe, NEW BT's:

An 8" fir brs. S. 78° E., 15.6 ft. dist. mkd. CW1/16S29CSBT.
An 8" fir brs. N. 41° E., 20.5 ft. dist. mkd. X S29CSBT.
Fence 50' South of corner. Corners East and West.

I used a compass with a 20° East variation and a steel tape,
measuring to face of BT blaze.

MONUMENT MARKED



RECEIVED AND
FILED

DEC 20 1976
John Liveira
JOHN LIVEIRA, County Clerk

By _____ Deputy